

Micropath[®] Corporation

2023 Montane Drive East • Tel: 303.526-5454 • Web: www.micropath.com
Golden, Colorado 80401-8099 • Fax: 303.526-0202 • E-Mail: sales@micropath.com

01 August 2007

The following message has been noted when starting the Pathanal program (formerly Micropath 2001):

ActiveX Component can't create object

This message may occur when the Microsoft DLL "DAO350.dll" is registered from the default location to another location on your PC.

Information provided by Microsoft has lead us to believe that this can occur if SQL is present and the DLL has been registered elsewhere on the PC instead of the "C:\Program Files\Common Files\microsoft shared\DAO\" folder

To Re-Register the DLL, use the Windows Run command with the following script:

```
regsvr32 "C:\Program Files\Common Files\microsoft shared\DAO\dao350.dll"
```

To Un-Register the DLL, use the Windows Run command with the following script:

```
regsvr32 "C:\Program Files\Common Files\microsoft shared\DAO\dao350.dll" /u
```

Note: DAO350.dll must exist in the "C:\Program Files\Common Files\microsoft shared\DAO\" folder to be registered/un-registered with the above Run commands.